Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00097

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513				
Exit Meeting Contact: Chuck Tebbe Total Man Days: 2					
Pipeline Safety Representative(s): Valerie Schwing					
Company Representative to Receive Report: Michael Fuller	Emailed Date:				
Company Representative's Email Address: mfuller2@ameren.com	05/06/2015				

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Jerseyville	Valerie Schwing	Jerseyville/Virden	2	3/12/2015, 3/24/2015	Chuck Tebbe, Rodger Camerer

Statement of Activities

On March 12, 2015, Staff conducted a Field Audit for Ameren Illinois inspection unit Jerseyville/Virden in Jerseyville, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. During the Field Audit, on March 12, 2015, Staff examined customer meters, observed cathodic protection reading, examined regulator stations, examined a rectifier, and examined pipeline materials. On March 24, 2015, Staff conducted a PHMSA Form 15 Operator Qualification Field Inspection Protocol regarding locating underground facilities. Staff also observed odorant readings and levels.

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00097

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]